

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---



14201 Creve Coeur Airport Hangar K2
St. Louis MO 63146

N#: N517FA S/N: 517/2020 Type: Bristell NG5 ACTT: 549.7 Tach: 429.9
Date: 12-10-2022

Performed 100 Hour Inspection in reference to Bristell Maintenance Manual
Specific to type Aircraft
Placarded Passenger Side Pedal Adjustment Handle inoperative.
Serviced Engine per Rotax Maintenance Manual, see Engine Log Book Entry.

I certify this aircraft has been inspected on ^{12/10/2022}~~09/27/2022~~ in accordance with BRM Aero's inspection procedures and was found to be in a condition for safe operation.

Joseph V. Ord LSRM-A 3438415 pending (issued: 9/11/2022 by Kansas City FSDO)

JOE 12/10/2022

**Light Sport
& ROTAX
Specialists**
 14201 Creve Coeur Airport Rd.
 Hangar K2
 St. Louis MO 63146



