

YEAR
20

RECORDING
TACH

TODAY'S
FLIGHT

TOTAL
TIME IN

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number



GATEWAY FLIGHT SOLUTIONS – 14301 CREVE COEUR AIRPORT RD – ST LOUIS MO 63146

LOGBOOK ENTRY- Airframe

AIRCRAFT: N9961W MODEL: PA28-140 TACH: 2320 S/N: 28-23508 DATE: 18-FEB-22

1) Performed an Annual Inspection. Inspection per Piper Maintenance Manual & FAR43 Appx D As a guide.

2) C/W FAR 91.207 ELT check Battery PN BP-1010 Due MAR 24.

3) C/W AD 17-14-05 Oil Cooler Hoses by Bend Test.

4) C/W AD 76-07-21RI Bendix Ignition Switch C/W 100 HR Recurring by Switch Rotation All good @ this time.

5) Cleaned & Repacked Wheel Bearings Checked Brakes Safeties Axle Nuts.

6) Cleaned Airframe Fuel Filter, Leak Checked good.

I certify that this Aircraft Has Been Inspected in accordance with an Annual Inspection & Determined to Be in Airworthy Condition.

Mike Walta  IA/AP AP3458994IA Date 2-18-22
